

problem Mercedes Audio Radio with display shows wait (codelocked)

If the Display shows / says "WAIT" then the unit is codelocked. If you leave it switched on for up to two hours a further attempt at code entry should be possible.

Get Mercedes Radio Code from Decode service